



Diagram	Heineger P/N	JCS P/N	Description
10	707-833	151799	PCB clipper
6	707-855	151800	Rubber tap
4	707-847	151801	Turning lever
5	707-848	151802	Seal
3	707-856	151803	Circlip DIN 6799 Ø3,2
2	707-886	151804	Washer Ø4x0,5
1	707-800-20	151805	Excentric cog wheel incl. ball bearing
8	707-854	151807	Blade support
13	707-846	151808	PT-screw Kombitorx KA30x8
9	707-800-25 C	151813	Blade lock
21	707-882	155882/170698	Rubber foot Pro3000i
22	707-557	165869	PT-screw Kombitorx KA30x16
16	707-600-11	165871	Charger Pro3000i
7	707-600-21	165872	Motor Pro3000i complete
14	707-620	165873	Li-Ionic battery 078003 7.4V/1.6 Ah
11	707-621	165874	Motor housing set Pro3000i complete
12	707-637	165875	Screw caps
17	707-638	165876	Upper housing Pro3000i charger
20	707-639	165877	Baseplate Pro3000i charger
19	707-640	165878	PCB charger pro3000i
18	707-641	165879	Light guide
23	707-648	165880	Power supply unit 110-240V without plug
27	707-898	165899	Plug Pro3000i US
15	None	Various	Oster blade set